



The ratio ( $R$ ) of the compressor is the slope of the curve above the threshold.

$$R = 10/5 = 2$$