



The ratio (R) of the compressor is the slope of the curve above the threshold.

$$R = 10/2 = 5$$